

City of Pompano Beach

Department of Development Services Building Inspections Division

100 W. Atlantic Blvd Pompano Beach, FL 33060 **Phone:** 954.786.4669 **Fax:** 954.786.4677

Building Safety Inspection Program Re-Inspection Affidavit

BORA Policy #05-05

Building Address:	Safety Inspection Report Permit #: 21-6037
Bermuda House Condominium Association Inc.	
328 N Ocean Blvd	Restoration Permit Number(s): 23-2594
Pompano Beach, Florida 33062	
TO: Property Owner Bermuda House Condominium Asso	ciation Inc
According to the requirements of BORA Policy #05-0 County Building Safety Inspection Report, COPB Per	5, Section 5, I have re-inspected the areas noted on the original Broward rmit / Case # 21-6037
Select options below that apply:	
Structural Repairs Completed	Electrical Repairs Completed Both Repairs Completed
•	ed repairs noted in the original Broward County Building Safety Inspection detailed in the referenced Restoration Permit Number(s).
■ To the best of my knowledge and belief, the requir Report were minor in nature, did not require permit,	ed repairs noted in the original Broward County Building Safety Inspection and were successfully completed.
☐ This report satisfies the requirements of the initial Inspection report completed under COPB Permit / C	25-year inspection based on the subsequent 10-year interval Building Safety ase #
	ither electronically with electronic signature/seal, or hand delivered if tisfy the requirements of Section 5, BORA Policy #05-05, Broward County
ACKNOWLEDGMENT	
FOR DIGITALLY SIGNED	Engineer Signature of Reporting Inspector, Seal AND Date D AND SEALED DOCUMENTS: THIS ITEM HAS BEEN DIGITALLY SIGNED AND J KRANZ, PE ON THE DATE ADJACENT TO THE SEAL. PRINTED COPIES
OF THIS DOCUMENT V SEALED AND THE SIGN FOR PRINTED DOCUM	WITH ONLY THE DIGITAL SEAL ARE NOT CONSIDERED SIGNED AND NATURE MUST BE VERIFIED ON ANY ELECTRONIC COPIES. ENTS: THIS ITEM MUST BEAR THE ORIGINAL RAISED OR WET SEAL AND
No. 49453 DATED SIGNATURE AF	FIXED BY EDWARD J KRANZ TO BE CONSIDERED SIGNED AND SEALED.
Printed Name of Reporting Inspector: Edward Kranz, PE	
Address of	Reporting Inspector: Covenant Engineering, Inc
SOME EN	2023.09.01 4149 SW 47th Ave, Suite 3C, Davie, Florida 33314
·///////// · · · · · · · · · · · · · ·	1:46:01 -04'00'
State of Florida Registration #: 49453	Email: edkranz@covenantmep.com Telephone #: 954-894-9112